
PRIORITY:	Normal
DATE:	November 19, 2001
TITLE:	Using the T3000 tool to remove ribbon cables
ECO REFERENCE:	N/A
PRODUCT(S) AFFECTED:	AlphaEclipse™ 3500 series signs
SUMMARY:	These instructions show how to use the T3000 extraction tool to remove a ribbon cable from its connection header.

Introduction

The T3000 is a special tool for removing a ribbon cable from its connection header.

This tool is intended for use with the ribbon cables and headers in AlphaEclipse™ 3500 series outdoor signs.

The T3000 extraction tool can be obtained through Adaptive Micro Systems.



Figure 1: T3000 extraction tool

© Copyright 2001 Adaptive Micro Systems, Inc. All rights reserved.

Adaptive Micro Systems • 7840 North 86th Street • Milwaukee, WI 53224 USA • 414-357-2020 • 414-357-2029 (fax) • <http://www.adaptivedisplays.com>

The following are trademarks of Adaptive Micro Systems: Adaptive, Alpha, AlphaNet plus, AlphaEclipse, AlphaPremiere, AlphaTicker, AlphaVision, AlphaVision InfoTracker, Automode, BetaBrite, BetaBrite Director, BetaBrite Messaging Software, Big Dot, PPD, Smart Alec, Solar, TimeNet



The distinctive trade dress of this product is a trademark claimed by Adaptive Micro Systems, Inc.

Due to continuing product innovation, specifications in this manual are subject to change without notice.


Related documentation

Document name	Part #	Description
Using the T3000 Extraction Tool to Remove Ribbon Cables	TechVideo #01-0001	The video companion to this TechMemo.
Guidelines for Controlling Electrostatic Discharge (ESD) Damage	TechMemo #00-0005	Basic procedures for preventing static damage to sensitive sign components.
AlphaEclipse™ 3500 Series Sign Installation and Service Manual	9711-6009	A guide for installation and field-serviceable repairs for an AlphaEclipse™ 3500 series outdoor sign.

Instructions



1. Remove power from the sign.
2. Open the sign. See the **AlphaEclipse™ 3500 Series Sign Installation and Service Manual** for details.
3. Locate ribbon cable to be removed. Attach T3000 to ribbon cable header:



4. Gently rock T3000 back and forth while pulling ribbon cable off of the connector.
5. Replace ribbon cable.
6. Close the sign. See the **AlphaEclipse™ 3500 Series Sign Installation and Service Manual** for details.